

SPEED INDICATOR RESULTS FOR AUGUST 2026


All speed indicators calculate the data using what is known as the 85th percentile speed which is the exact speed at or below which 85% of vehicles travel on a specific section of road under free-flowing conditions.

The table below represents the movements in and out of the village using data collected by the three speed indicators within the village of Helpingham.


Location	Date	Direction	Number of vehicles	Average speed (mph)	Maximum Speed (mph)	85 th Percentile Speed (mph)
Hale Rd	Aug 26	Incoming	18449	24.29	45	26
Hale Rd	Aug 26	Outgoing	18135	26.17	50	29
Station Rd	Aug 26	Incoming	11159	27.23	68	31
Station Rd	Aug 26	Outgoing	12877	29.70	66	34
Highgate	Aug 26	Incoming	16401	29.25	60	31
Highgate	Aug 26	Outgoing	15839	30.8	65	34

The following charts show the range of speed in and out of each location.

Hale Road



Station Road



Highgate

